



**Recall of Klein
1994 and 1995 Quantum Pro Neck Stems
Verification of Recall**

Klein Bicycle Corporation has filed a report with the Consumer Product Safety Commission indicating that a defect may exist in the handlebar stems of Klein Quantum Pro Road bicycles manufactured between February 1994 and May 1995. This defect may result in the handlebars separating from the bicycle during use. If you purchased a Klein Quantum Pro during 1994 or 1995, stop using it and bring it to your Klein dealer for inspection. If your part was manufactured between February 1994 and May of 1995, it will be replaced free of charge. If you have further questions, call Klein customer service at 1-800-509-RIDE.

October 4, 1994
For Immediate Release
Contact: Mary Monroe
(414) 478-2191 Ext 2482
Bill Van Lieshout Ext 2526

TREK RECALLS 1994 MODELS DUE TO BOTTOM BRACKET PROBLEM

Waterloo, WI (October 4, 1994)--Effective immediately, Trek USA is announcing a voluntary recall regarding a potentially serious problem with bottom bracket spindles found on various Trek 1994 models.

The following 1994 Trek models are affected:

2200
7000
7000 SHX
7300
7600
7900
8000
8700

The parts are bottom bracket spindles manufactured by K.S.S. Specifically, the concerns are for the "TLS" and "TLS Super" bottom brackets.

Trek is requesting that all sales and shipment of both the bicycle models and aftermarket items listed be discontinued.

Dealers are requested to:

1. Discontinue sales and distribution of the aforementioned bicycle models.
2. Immediately inform and discontinue operation of the affected models already in the hands of the customer.

Trek has voluntarily advised the Consumer Product Safety Commission of our concerns.

###

October 4, 1994
For Immediate Release
Contact: Mary Monroe
(414) 478-2191 Ext 2482
Bill Van Lieshout Ext 2526

FISHER RECALLS 1994 MODELS DUE TO BOTTOM BRACKET PROBLEM

Waterloo, WI (October 4, 1994)--Effective immediately, Fisher Bicycle Corporation is announcing a voluntary recall regarding a potentially serious problem with bottom bracket spindles found on various Fisher 1994 models.

The following 1994 Fisher models are affected:

Montare
Paragon
Mt. Tam
Supercaliber

The parts are bottom bracket spindles manufactured by K.S.S. Specifically, the concerns are for the "TLS" and "TLS Super" bottom brackets.

Fisher is requesting that all sales and shipment of both the bicycle models and aftermarket items listed be discontinued.

Dealers are requested to:

1. Discontinue sales and distribution of the aforementioned bicycle models.
2. Immediately inform and discontinue operation of the affected models already in the hands of the customer.

Fisher has voluntarily notified the Consumer Product Safety Commission of our concerns

###